



NUMBER: 08-018-07

GROUP: Electrical

DATE: June 23, 2007

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Mopar Remote Start System - RKE - Intermittent Operation Or Alarm May Sound

OVERVIEW:

This bulletin involves the installation of a Mopar Remote Start System - Service Repair Kit.

MODELS:

2007	(DR/DH/D1/DC)	Ram Truck (1500/2500/3500)
2007	(HB/HG)	Durango / Aspen
2007	(JK)	Wrangler
2008	(JS27)	Sebring Convertible
2007	(JS)	Sebring
2007 - 2008	(JS)	Avenger
2007	(KA)	Nitro
2007	(MK49)	Compass
2007	(MK74)	Patriot
2007	(PM)	Caliber

NOTE: This bulletin applies to vehicles installed with a Mopar Remote Start Installation Kit.

SYMPTOM/CONDITION:

On vehicles that have had a Mopar Remote Start installation Kit installed by a dealer, the customer may experience one or more of the following conditions:

A). ON ALL VEHICLES:

An intermittent operation of the Remote Keyless Entry (RKE) system. At times, the RKE system may not function as designed. This may include intermittent operation of: lock/unlock mode, remote start mode, or panic mode. The vehicle may be operated manually without issue using the ignition key to open or lock the door, and to start the vehicle.

B). ON RAM TRUCK AND DURANGO/ASPEN VEHICLES ONLY:

The vehicle alarm may sound when the RKE system is activated by use of the key FOB. Deactivation of the vehicle alarm occurs when the vehicle engine is started using the

ignition switch and key.

The above condition(s) may be present **ONLY** if one of the following specific kit part numbers for the Mopar Remote Start Installation Kit had been installed previously on the suspect vehicle.

MOPAR REMOTE START INSTALLATION KIT P/N (with possible condition)	VEHICLE APPLICATION
82211214	2007 DR/DH/D1/DC
82210224AG	2007 HB/HG
82209363AG	2007 PM
82209364AG	2007 MK49/MK74
82209982AG	2007 JK
82209984AG	2007 KA
82210210AG	2007-2008 JS

DIAGNOSIS:

If the customer has experienced the above condition, and the vehicle has had a Mopar Remote Start Installation Kit installed, then perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68035610AA	Service Repair Kit - Mopar Remote Start (DR/DH/D1/DC - HB/HG)
1	68035609AA	Service Repair Kit - Mopar Remote Start (JK/JS/KA/MK/PM)

REPAIR PROCEDURE:

Install the Remote Start Service Repair Kit. Refer to the detailed instructions included with the repair kit.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-99-25-91	Install - Remote Start Service Repair Kit (B) - DR/DH/D1/DC/HB/HG	0.5 Hrs.
08-99-25-92	Install - Remote Start Service Repair Kit (B) - JK/JS/KA/MK/PM	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------